

**LEACHATE COLLECTION WELLS
OM&M MONITORING AND BAILING DATA SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

DATE: August 13, 2007

TECHNICIAN NAME: ROCKA, P. S.

TECHNICIAN SIGNATURE Paul S. Rocka

WELL ID	BOTTOM OF WELL AFTER CONSTRUCT-ED [TOTAL DEPTH] (ft)	MEASURED BOTTOM OF WELL [TOTAL DEPTH] (ft)	GAUGING TIME		DEPTH TO LIQUID (ft)						HEIGHT OF LIQUID COLUMN (ft)		VOLUME OF LIQUID REMOVED (gallons)	COMMENTS
			Start	Finish	Start			Finish			Start	Finish		
					1 st Rdg.	2 nd Rdg.	3 rd Rdg.	1 st Rdg.	2 nd Rdg.	3 rd Rdg.				
LC-1	22.25	22.24	1605	1620	19.20	19.20	19.20	22.13	22.13	22.13				
LC-2	21.90	21.90	1626	1647	13.36	13.36	13.36	21.41	21.41	21.41				
LC-3	22.20	22.20	1655	1659	21.93	21.93	21.93							LESS THAN A FOOT
LC-4	21.90	21.90	1705	1725	13.81	13.81	13.81	21.08	21.08	21.08				

W:\InterimOpMain+Mon\LeachateCollectionWells\WorkPlan+FieldForms\February2007\Feb507LC-WellsM&B(YF1).doc

**LEACHATE COLLECTION WELLS
OM&M INSPECTION SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

INSPECTOR'S NAME	INSPECTOR'S SIGNATURE	INSPECTION TIME	INSPECTION DATE
ROCKA, P.J.	Paul S. Rocha	1600	August 13, 2007

ITEM OF POTENTIAL CONCERN	CONDITIONS OBSERVED				COMMENTS	CHECK (✓) BELOW WHEN COMPLETED
	WELL ID LC-1	WELL ID LC-2	WELL ID LC-3	WELL ID LC-4		
Wellhead (well box, cover, gasket, concrete)	OK	OK	OK	OK		✓✓✓✓
Well Casing and Cap/Plug	OK	OK	OK	OK		✓✓✓✓
Liquid Present in Well Box	NO	NO	NO	NO		✓✓✓✓
Other:						
Other:						
Other:						

W:\InterimOpMain+Mon\LeachateCollectionWells\WorkPlan+FieldForms\February2007\Feb107LC-WellsInspection(YF).doc

DAILY FIELD REPORT

JOB NAME: WASTE DISPOSAL, INC. (WDI)	PROJECT NUMBER: 125154/001400	DATE: 8/13/2007
LOCATION: Santa Fe Springs, California	WEATHER: <u>Hot</u>	DAY: Monday
OM&M CONTRACTOR: TRC	FOREMAN:	
FIELD TECHNICIAN: <u>ROCKA P. J.</u>	INSPECTION/TESTING OF: LEACHATE MONITORING/CONTROL SYSTEM	

SUMMARY OF OPERATIONS/WORK PERFORMED::

ARRIVE @ SITE.. OPEN GATE..

DRIVE AROUND.. PREPARED TRUCK..

Gauge well. CLEANING IT OFF EVERY TIME

I SOUND (GAUGE) IT. THEN BEGAN BAILING..

AFTER SEVERAL PULLS BEGAN GAUGING

ONCE AGAIN 3X MORE ACTUALLY..

EVERY TIME I MADE SURE IT WAS

CLEANED OFF. AFTER CLEAN OFF WELL

BACK & MOVE ON TO NEXT WELL..

REPEATED ALL STEPS FOR EACH WELL..

THEN DROVE BACK TO SHOP WHEN

FINISH.

Paul Rocka

TRC
Customer-Focused Solutions

Note: Specific System Data and Observations are Included on "OM&M Inspection Sheets" and "OM&M Monitoring and Bailing Data Sheets"

DAILY FIELD REPORT
WASTE DISPOSAL, INC
SANTA FE SPRINGS, CALIFORNIA

TRC

FIGURE J.1